

# COMFORTINA 42

Year 1999





### **COMFORTINA 42**



#### Main Info

Model	Comfortina 42
Manufacturer	Comfortbåtar Marine AB (SWE)
Designer	Thomas Bern
Category	Performance cruiser
Year	1999
Location	Côte d'Azur/Südfrankreich
Flag	Germany
VAT status	EU-VAT paid
Material	GRP
Rig	Sloop
Cabins	2
Berths	6

### Dimensions & Material

LOA	12.86 m
LWL	11.50 m
Beam	3.85 m
Draft	2.10 m
Displacement	9.5 t
Sail area	88 m²
Engine	YANMAR 4JH-3E
Power	56 PS/41 KW
Drive	Saildrive with folding propeller
Fresh water	500 L
Fuel	250 L
Holding tank	140 L

### **Key Facts**

- Exclusive, beautiful teak interior
- Light use: (log: 5.840 nm, engine: 690 h)
- Excellent performance
- Very seaworthy yacht
- Electric genoa winches

### Description

Strong and exclusive performance-cruiser built by Comfortbåtar Marine AB in Sweden. The Comfortina 42 is not only fast, but also a very safe and seaworthy yacht with plenty of living space and luxury below decks. Beautiful teak interior with many well finished details, selected veneers and a lot of solid wood. Plenty of storage space in lockers, drawers and the large cockpit locker to starboard. Well equipped firsthand Comfortina 42. Regular technical service by professional shipyard. The yacht can be inspected any time upon appointment in the South of France. Option: The mooring in Port Grimaud can be leased or purchased.



Generated on: 26 07 2025

### Rigging/Sails

- Rigged with a keel stepped, 9/10 fractional SELDEN mast
- Two sets of aftswept spreaders
- Genoa furler FURLEX 300S with drum below decks
- Spinnaker pole
- Manual backstay adjuster
- Aluminum tubes for rigging screws

- Running backstays
- Sails: Fullbattened mainsail ROYAL-Sails Pentex Radial approx. 44 m²
- FREDRIKSEN ball bearing sliders with lazy jacks and boom cover
- Furling genoa ROYAL-Sails Pentex Radial approx. 50 m<sup>2</sup> with UV-protection
- Jib ROYAL-Sails approx. 35 m²

#### Deck

- Teakdeck on cockpit floor, cockpit seats and swim platform
- Electric anchor windlass LEWMAR 1.000 W with BRUCE-anchor 20 kg and 50 m anchor chain 8 mm
- Electric genoa winches ANDERSEN 52.2STE
- Mainsheet in T-System with mainsheet winches ANDERSEN 46.2ST
- Coachhouse winches ANDERSEN 40.2ST
- Sprayhood
- Spring cleats

- Teak cockpit table
- Swim ladder
- Stern shower hot/cold
- Teak outboard bracket on pushpit
- Teak rubbing strake with stainless steel profile on hull sides
- Stainless bow protection rail



Generated on: 26 07 2025

#### Layout/Interior

- Beautiful teak interiors in best Scandinavian boat builder's tradition
- 3 cabin layout with owner's cabin and owner's heads forward
- Saloon with U-shaped dinette to port
- Longitudinal sofa to starboard on folding saloon table
- L-shaped galley to port aft with worktop in CORIAN
- Gas stove (3 burners and oven)

- Large electric coolbox with water cooled ISOTHERM 3200 SP cooling unit
- Double sink
- Forward facing charttable to starboard aft
- Aft cabin with double berth and locker to port
- Second heads compartment to starboard with access to cockpit locker
- Carpet throughout the yacht

#### Navigation/ Electronics

- Instruments: RAYTHEON ST60 log, ST60 depth sounder, ST60 wind
- Autopilot ROBERTSON AP20
- Compass
- GPS/chartplotter MAGELLAN Nav 6510
- VHF SHIPMATE RS8400

- NAVTEX receiver FMD20
- Radio/CD-player PHILIPS
- R[&]R combi antenna "Hawaii" TV flatscreen in saloon
- Ship clock
- Barometer

#### Safety

- Lifejackets
- Horseshoe with floating line

Manual and electric bilge pump



Generated on: 26 07 2025

#### Accessories

- Sun awning
- Cockpit cover
- Cover for furling genoa
- Fenders

- Mooring lines
- Crockery and cutlery
- Spare parts
- Tools

#### **Brokerage Liability Disclaimer**

All information especially regarding the VAT-status of a yacht has been supplied by third parties. It is non-binding and without guarantee, subject to error and alteration. Our brokerage relies exclusively on information supplied by the vendor carefully compiled and checked by us to the best of our knowledge. Hence, a liability for correctness and completeness of provided information cannot be assumed.

Generated on: 26.07.2025













Generated on: 26 07.2025













Generated on: 26.07.2025













Generated on: 26.07.2025















